

FIG.1






FIG.2




**FIG.3**




20250323000000


03863-0303




**FIG.5(a)**




**FIG.5(b)**



**FIG.6**




**FIG.7**




# FIG.8

category name
particle
flaw
pattern defect (short)
pattern defect (open)
voltage contrast defect (open)
voltage contrast defect (short)
other


# FIG.9




# FIG.10




# FIG.11



# FIG.12



# FIG.13





# FIG.14

	surface shape information		
	protrusions	indentations	other
short	particle	flaw	pattern defect (short)
half-short	particle	flaw	pattern defect (short)
open	particle	flaw	pattern defect (open)
half open	particle	flaw	pattern defect (open)

# FIG.15




FIG.16






FIG.17



# FIG.18



# FIG.19




FIG.20




FIG.21




FIG.22





FIG.23



09223638 033004  
"0000" 9992860